# AGENDA ZONING COMMITTEE OF THE SAINT PAUL PLANNING COMMISSION Thursday, May 27, 2010 3:30 P.M. City Council Chambers Third Floor City Hall - Saint Paul, Minnesota

NOTE: The order in which the items appear on this agenda is not necessarily the order in which they will be heard at the meeting. The Zoning Committee will determine the order of the agenda at the beginning of its meeting.

#### APPROVAL OF MAY 13, 2010, ZONING COMMITTEE MINUTES

SITE PLAN REVIEW - List of current applications (Tom Beach, 651-266-9086)

#### **NEW BUSINESS**

#### 1 10-314-094 Yee Fang

Re-establishment of nonconforming use as a duplex 924 Forest St, between Sims and York R4

Luis Pereira 651-266-6591

#### 2 10-320-786 Olga Zoltai

Establishment of legal nonconforming use as 8 residential units: 6 in main building, 2 in carriage house

476 Summit Ave, SW corner at Lawton

RT2

Merritt Clapp-Smith 651-266-6547

#### 3 10-320-034 Renaissance Fireworks

Conditional use permit for outdoor seasonal sales of fireworks 1440 University Ave W, west side between University and St. Anthony


Patricia James

651-266-6639

#### **ADJOURNMENT**

ZONING COMMITTEE MEMBERS: Call Allan Torstenson at 266-6579 or Samantha Langer at 266-6550 if you are unable to attend the meeting.

APPLICANT: You or your designated representative must attend this meeting to answer any questions that the committee may have.



#### ZONING COMMITTEE STAFF REPORT

1. FILE NAME: Yee Fang

FILE # 10-314-094

2. APPLICANT: Yee Fang

**HEARING DATE:** May 27, 2010

3. TYPE OF APPLICATION: Re-establishment of a Nonconforming Use Permit

4. LOCATION: 924 Forest St, between Sims and York

5. PIN & LEGAL DESCRIPTION: 282922310111; Auditors Subdivision No 7 Lot 10 Blk 3

6. PLANNING DISTRICT: 5

7. **ZONING CODE REFERENCE:** §62.109(d)

**PRESENT ZONING: R4** 

8. STAFF REPORT DATE: May 27, 2010

BY: Luis Pereira

9. DATE RECEIVED: April 27, 2010

60-DAY DEADLINE FOR ACTION: June 26, 2010

A. **PURPOSE:** Re-establishment of nonconforming use as a duplex.

B. PARCEL SIZE: 6,600 sq. ft. (0.15 acres) (50 feet wide by 132 feet deep)

C. **EXISTING LAND USE:** Duplex (R4)

D. SURROUNDING LAND USE:

North: Duplex (R4)

East: Single Family Detached Home (R4)

South: Duplex (R4)

West: Single Family Detached Home (RT1)

- E. **ZONING CODE CITATION:** §62.109(d) lists the conditions under which the Planning Commission may grant a permit to re-establish a nonconforming use.
- F. HISTORY/DISCUSSION: County tax records indicate that the property was built in 1889. A PED Zoning Map from the 1970s shows this property as a duplex. DSI records also indicate this property has been a duplex for the past 10 years, a period over which it had multiple owners. On November 15, 2001, the property was first put on the City's Vacant Building List as a duplex. On January 15, 2004, the property received a rental registration as a duplex. A Truth in Sale of Housing (TISH) report from April 8, 2004 again identifies the property as a duplex. A series of complaints followed over the next several years about inadequate trash removal, snow removal, and tall grass/weeds. A TISH report from December 15, 2006 again identifies the property as a duplex. A Certificate of Occupancy was approved for the property on March 3, 2007 for two units. Numerous complaints about the property followed. On June 2, 2008, gas/electric utilities were shut off for unit 1. The property returned to the City's Registered Vacant Building List on June 9, 2008, as a Category 2 duplex; the owner at this time was listed as "R And J Enterprises Trustee/Forest 24 Trust." In January 2009, a Parks summary abatement record shows the need for the removal of snow and ice from the front walk, the listed owner at this time was Deutsche Bank Nat Trust Co. A Code Compliance Report was requested by the listed owner on February 26, 2009 - "MN REO Property Maintenance" - and sent on March 19, 2009. Complaints about tall grass/weeds in August 2009 and inadequate snow removal followed in December 2009 before the property was purchased by the applicant in 2010.
- G. **DISTRICT COUNCIL RECOMMENDATION:** The Payne Phalen District 5 Planning Council had not provided a written recommendation on this application when the staff report was composed.

#### H. FINDINGS:

- 1. The applicant/owner states he purchased the property on February 24, 2010 as a duplex, and it was marketed as a duplex. Floor plans submitted by the applicant show two bedrooms and one bathroom on the first floor, and three bedrooms, 1 bath on the 2<sup>nd</sup> floor. Each unit also has a living room and kitchen, and the building has two separate gas, electrical meters, and furnaces
- 3. A Code Compliance Report, dated March 19, 2009 identifies building maintenance items

- including window replacements and siding repairs, as well as necessary electrical, plumbing, and heating system corrections. The Code Compliance Report is now expired.
- 2. Section 62.109(e) states: When a nonconforming use of a structure, or structure and land in combination, is discontinued or ceases to exist for a continuous period of three hundred sixty-five (365) days, the planning commission may permit the reestablishment of a nonconforming use if the commission makes the following findings:
  - (1) The structure, or structure and land in combination, cannot reasonably or economically be used for a conforming purpose. This finding is not met. The Pro Forma Information Sheet for Duplex Conversion Cases submitted by the applicant does not indicate the cost of rehabilitation work to be performed on the property (for either the single family or duplex use). The applicant states that if the building remains a duplex, it will be affordable to bring the building up to Code (including heating, plumbing, electrical, and general building repair), and no remodeling work would be needed. If required to convert to a single family use, the applicant states that disconnecting/removing systems associated with a second unit in the building would cost thousands of dollars. However, DSI records also contain a Residential Use Affidavit signed by the applicant on February 10, 2010 that indicates the property was purchased with the understanding that it would need to be converted to a single family dwelling. The affidavit includes a note written by DSI staff on February 17, 2010 that the property is currently a duplex but that its de-conversion to single family use would be verified during a field inspection.
  - (2) The proposed use is equally appropriate or more appropriate to the district than the previous nonconforming use. This finding is met, as the proposed duplex use is the same as the property's current duplex use.
  - (3) The proposed use will not be detrimental to the existing character of development in the immediate neighborhood or endanger the public health, safety, or general welfare. This finding is met if a new Code Compliance Report is requested and generated and the repair items that are identified in the report are performed.
  - (4) The proposed use is consistent with the comprehensive plan. This finding is met. The property falls within the Comprehensive Plan's Residential Corridor designation on the Generalized Future Land Use Map, which supports residential uses between 4 and 30 dwelling units per acre. The proposed duplex use on this property has a density of approximately 13 units per acre. The applicant also points to the presence of only one single family detached home on this block (930 Forest) between Sims Ave, Forest, and Duchess Streets as support for this property's use as a duplex (Metropolitan Council 2005 land use maps shows three duplexes, two multifamily buildings, and an undeveloped parcel on this block, but more recent County tax records show 930 Forest St. as a single family dwelling).
  - (5) A notarized petition of two-thirds of the property owners within one hundred (100) feet of the property has been submitted stating their support for the use. This finding is met. The petition was found sufficient on April 29, 2010: 10 parcels eligible; 7 parcels required; 7 parcels signed.
- 3. The Planning Commission has established guidelines for applications to establish legal nonconforming use status for duplexes. While not themselves requirements, these guidelines lay out additional more objective factors the Planning Commission wishes to consider in determining if the required findings for granting nonconforming use permits listed in §62.109 of the Zoning Code can be made. The Planning Commission's Duplex Conversion Guidelines state that for applications for nonconforming use permits for duplexes in residential districts, staff will recommend denial unless the following guidelines are met:

- A. Lot size of at least 5,000 square feet with a lot width or front footage of 40 feet. This guideline is met, as the lot is 6,600 square feet in size, and has a front footage of approximately 50 feet.
- B. Gross living area, after completion of duplex conversion, of at least 1,500 square feet. Neither unit shall be smaller than 500 square feet. This guideline is met. The floor plan for unit 1 shows 781 square feet of floor area, not including the entrance area or rear landing area. The floor plan for unit 2 shows 862.9 square feet of floor area, not including the front door or back door landing areas. The total gross living area of the two units exceeds 1,500 square feet (a total of 1,643.9 square feet, not including entrance area or landing areas).
- C. Three off-street parking spaces (non-stacked) are preferred; two spaces are the required minimum. This guideline is met if three off-street parking spaces are provided as shown to access Duchess Street on the submitted "site plan for parking." The applicant states that currently there are two existing off-street spaces to the rear of the house located off of Duchess, but he can provide one additional space.
- D. All remodeling work for the duplex is on the inside of the structure unless the plans for exterior changes are approved by the Board of Zoning Appeals as part of the variance. (The Planning Commission will approve these changes for the cases they handle.) This guideline is met, as no items identified in the Code Compliance Report would result in the physical alteration of the structure that is visible from the exterior.
- E. For the purpose of protecting the welfare and safety of the occupants of any structure that has been converted into a duplex without the necessary permits, a code compliance inspection shall be conducted and the necessary permits obtained to bring the entire structure into conformance with building and fire code standards; or the property owner must, as a condition of the approval, make the necessary improvements to obtain the necessary permits and bring the entire structure into building and fire code compliance within the time specified in the resolution. This guideline is met if a new Code Compliance Report is requested and performed and the applicant makes the identified corrections to the property.

The application for the permit shall include the petition, a site plan meeting the requirements of section 61.401, floor plans, and other information as required to substantiate the permit. This finding is met.

I. STAFF RECOMMENDATION: Based on the finding # 2(1) above, staff recommends denial of the re-establishment of nonconforming use as a duplex.

NONCONFORMING USE PERMIT APPLICATION
Department of Planning and Economic Development
Zoning Section
1400 City Hall Annex
25 West Fourth Street
Saint Paul, MN 55102-1634
(651) 266-6589

yZonling Office Use Only File #: 10 31 2514 Tentative Hearing Date:

•	282 023 0///
	Name Yel Fang
APPLICANT	Address 957 Reaney Ave
ECEIVE	Gity ST Paul st. Mn ZID 55106 (651) 771-8954 (715) Daytime Phone 379-5114
ADD ~ C 2010	lame of Owner (if different)
APR 6 2010	Contact Person (if different)Phone
and the state of t	
PROPERTY LOCATION	Address/Location 924 Forest St ST Paul mn 55106
	Legal Description Non Comforming Duplex
	Current Zoning (attach additional sheet if necessary)
TYPE OF PERMI	F: Application is hereby made for a Nonconforming Use Permit under provisions of Chapter 62, Section 109 of the Zoning Code:
.The permit is for:	Change from one nonconforming use to another (para. c)
	Re-establishment of a nonconforming use vacant for more than one year (para, e)
	<ul> <li>□ Establishment of legal nonconforming use status for use in existence at least 10 years (para. a)</li> <li>□ Enlargement of a nonconforming use (para. d)</li> </ul>
p	
į.	FORMATION: Supply the information that is applicable to your type of permit.
Present/Past Use	non comtorming Duplex
Proposed Use	non comforming Duplex
Attách additional s	heets if necessary
,	
	PdC 12/10
	1 1/2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	104.50
Attachments as re	quired  Site Plan Consent Petition  Affidavit
Applicant's Signat	ure Date 3/15/10 City Agent No. 10
	onforming use permit Revised 1/3/07

Re-establishment of nonconforming use for property address: 924 Forest St Saint Paul, Mn 55106

1. The structure, or structure and land in combination, cannot reasonably or economically be used for a conforming purpose.

The structure or structure and land in combination is reasonable and economically be used as a nonconforming duplex. This building was listed for sale as a duplex, I bought it on 2/24/10 as a duplex and will keep it as a duplex. The building was built on an oversize lot as legal 2 stories duplex building up and down with 2 bedrooms and 1 bath on 1<sup>st</sup> floor 3 bedrooms and 1 bath on 2<sup>nd</sup> floor. The building has 2 separate gas, 2 separate electrical meters, 2 separate furnaces, 2 separate kitchens and 2 cars parking space on the property.

There are 6 buildings on this parcel. 1<sup>st</sup> building 930 Forest St is a residential, 2<sup>nd</sup> building 924 Forest St is a duplex (propose property). 3rd building 920 Forest St is a duplex, 4<sup>th</sup> building 910 Forest St is an apartment, 5<sup>th</sup> building 902 Forest St is a duplex and the last 6th building of 890 Forest St is an apartment. The rest of the buildings in this neighborhood and adjacent are mix used combination of residential and duplexes. As a new owner of the property I would like to propose to the city of Saint Paul to consider my budget plan to invest into this property for number of reasons:

Disadvantage: Convert to residential I must spent thousands of dollars for licensing contractors to disconnect and remove all equipments which were not required in the building. I may have to spend thousands additional more budget to remodel all floors, bedrooms, kitchens and every thing in the building on top of the city of Saint Paul code compliances. (see code compliances DSI).

As we all know that Minnesota and all over the United State are in recession, jobs are out of touch, economy is getting worst, bad credit and banks are no longer interest to loan money. This duplex is livable condition and it is not a good idea with a tight budget to spent money to convert it to residential unless the building is endanger to public health, safety and general welfare for tenants and neighbors. Furthermore; to convert it to residential may not meet my financial goal to maximizing monthly income that I depend on this investment to generate income for my family. For example rent from this building as residential will be \$1000.00 per month compare to duplex can be \$1600.00 per month.

Advantage: Budget for nonconforming duplex contractors of heating, plumbing, electrical and general repair for the building can be affordable to bring every thing up to code to meet city of Saint Paul code compliances. Nonconforming duplex will not need to do any remodel and modification to the building, because every thing that are needed in the property for duplex already built with the building.

I will save thousands of dollars to do other important projects and reinvest more money to buy foreclosure and vandalism properties in the city of Saint Paul. These properties

will be fixed, cleaned with good maintenance and bring every thing up to code for citizens of this city to enjoy more safely. The investment can be financial sounded, generate more business incomes and tax revenues to serve the citizens of Saint Paul for affordable housing to raise families. At the same time I can make more monthly income from these investment properties to support my family financial needed.

2 .The proposed use is equally appropriate or more appropriate to the district that the previous nonconforming use.

Population of Saint Paul has grown to out number the same time with hundreds and hundreds of properties owners were defaulted their mortgage loans and these properties were forced to foreclosure and vandalism due to the real estate market, lost job no income to meet the monthly mortgage payment during this recession. This market is driving housing in demand the same as financial hardship can be found in almost every family household with in the community where we lived. I have seen more and more families were forced into duplex or apartment in order to afford rent payment because budget is limited.


This duplex is on an oversize lot in the area of housing demand and affordable to meet the need of today economy. It has a lot of spaces to meet the need of growing families to raise children and to enjoy for years to come. The parcel of this property was built on has total of 6 buildings on it but only 1 of them is a single residential. This building is more appropriate to re-establishment for nonconforming duplex because it's in the demand area to better serve in today housing need for city of Saint Paul's population.

3. The propose use will not be detrimental to the existing character of development in the immediate neighborhood or endanger the public health, safety, or general welfare.


The propose use to re-establishment of nonconforming duplex will not have any immediate effect and cause a significant change to the existing character of development in the neighborhood nor create any health, safety endanger to the public and general welfare because this nonconforming use of duplex has always been a legal duplex since it was built for nearly 100 years ago until I bought it. I found myself very hard to believe that this building may has been in the residential zoning where almost all of these buildings on this parcel are multiple units. This nonconforming duplex has not known to have any health, safety endanger nor significant effect to change the existing character of this neighborhood since the building was built nearly 100 years ago nor in the next 100 years from now.

Therefore; I would like to keep it as duplex with out converting to single residential. Again, this nonconforming duplex is not new to the immediate neighborhood and it has been enjoyed perhaps by hundred or thousand families who lived in this building after it was built nearly 100 years ago. The building has 2 cars parking on the property and I can make 1 additional space in the same area to accommodate for tenant parking.

Site plan for additional parking and floor plan of the building are enclosed.



Floor Plan unit 1




724 Forest Unit 2

FloorPlan unit 2

924 Forset St St Paul, mn 55106

Site Plan to: Parking



ts ssound

# SUMMARY INFORMATION SHEET. FOR DUPLEX AND TRIPLEX COVERSION CASES

Beyenty would be

Housing unit breakdown:	Existing	Proposed
Number of units	2	2
Number of bedrooms in each unit		
Unit 1	3	3
Unit 2	3	3
Unit 3		
Size of each unit in square feet		,
Unit 1	1200	1200
Unit 2	1400	1400
Unit 3		
Debt:		•
Initial principal amount	·	
Initial interest rate		
Term of mortgage/debt financing		
Time remaining on note		
Balance on existing debt		
lehabilitation		
Type of improvements:	·	
Plumbing, heating and electrical		
up to code.		

## PRO FORMA INFORMATION SHEET FOR DUPLEX AND TRIPLEX CONVERSION CASES

Continuation of Extra Units

SINGLE FAMILY

Required information	DUPLEX 7	Ar Backy see
. required information	With Continuation of Extr. Units in Structure	With Conversion of Structure to Legal Number of Units
<u>Income</u>		
Total monthly rent income for all units	1.600	1.000
Monthly income from structure other than rent		1,000
Existing vacancy (if any)		
Effective gross income (EGI) / month 1	\$,1600 -	\$ 1000
Effective Gross Income / year	\$ 192,00	\$ 12,000 -
Operating Expenses (Annual) 2	\$ -	\$
Maintenance	1000	1000
Insurance	1500	1500
Utilities (only include amount paid by landlord)	1440	1440
Other (identify)		
Taxes	2000	2000
Net Operating Income (Annual) 3	\$ 13260	\$ 6,060 -
Monthly debt / mortgage payment		J.
<u>Annual debt paγment</u>	.\$	\$ -
Rehab projects		
Total cost of improvements		
Monthly rehab debt payment		
Annual rehab debt payment	\$ - !	_
Cash Flow: profit, (loss) 4	\$ 13,2,60	6,060

NOTE: 1. Effective Gross Income = (Total rent income) - (Vacancy, if there is any)

<sup>2.</sup> Operating expenses are the sum of the next five lines, incl maintenance, insurance, utilities, taxes and others

<sup>3.</sup> Net Operating Income = (Effective Gross Income) - (Operating Expenses)

<sup>4.</sup> Cash Flow = (Net Operating Income) - (Annual debt payment)

### ZONING PETITION SUFFICIENCY CHECK SHEET

SCUP

REZONING

FIRST SUBMITTED	RESUBMITTED
date petition submitted: $4-6-10$	DATE PETITION RESUBMITTED:
DATE OFFICIALLY RECEIVED:	DATE OFFICIALLY RECEIVED:
PARCELS ELIGIBLE: /O	PARCELS ELIGIBLE: 10
PARCELS REQUIRED:	PARCELS REQUIRED: 7
PARCELS SIGNED:	PARCELS SIGNED:
CHECKED BY: PANI Dubruie	L DATE: 4-13-10
And Dubrain	eL 4-29-10

STAMP Property Activity History	ity History				
Address	<u>In Date</u>	# QI	Status	Type	Description
924 Forest St	4/27/2010	10 314094	Pending	1	Applicant: Yee Fang - Re-establishment of
		-		φ.	nonconforming use as a duplex
				Permit-Reestablishment -	
924 Forest St	4/16/2010	10 307342	. Open	GT - General Activity Tracking	GT - General Activity Tracking Return of application for Re-establishment of
924 Forest St	4/15/2010	10 247212	Open	RE - Real Estate Assessments	Nonconforming Use Owner: Yee Fang
924 Forest St Fl 1	4/15/2010	10 247212	Open	RE - Real Estate Assessments	Owner: Yee Fang
924 Forest St Fl 2	4/15/2010	10 247212	Open	RE - Real Estate Assessments	Owner: Yee Fang
924 Forest St	2/26/2010	10 113434	Resolved	rt - Snow	Snow Walk
924 Forest St	12/30/2009	. 09 521171	Resolved	Walk - Complaint CS - CSO Complaint - Snow	Snow Walk
				Walk - Complaint	
924 Forest St	8/25/2009	09 259691	Resolved	CS - CSO Complaint - Tall Grass - Complaint	TGW
924 Forest St	1/27/2009	09 016389	Closed	2	Owner: Deutsche Bank Nat Trust Co - Remove snow and
				Abatement - Snow Ice	ice from public sidewalk full width, salt and sand as
924 Forest St	1/16/2009	09 010765	Resolved	CS - CSO Complaint - Snow	snow walk
924 Forest St	1/2/2009	09.000545	Closed	PA - Parks Summary	Owner: R And I Enterprises Trustee/Envect 24 Trust
				Abatement - Snow Ice	Remove snow and ice from public sidewalk full width,
					salt and sand as needed.
924 Forest St	9/29/2008	08 157105	Closed	PA - Parks Summary	Owner: R And J Enterprises Trustee/Forest 24 Trust -
	· .			Abatement - Garbage Rubbish	Remove all discarded furniture, scrapwood, metal, bags, and boxes.
924 Forest St	9/29/2008	08 157106	Closed	PA - Parks Summary	Owner: R And I Entorneises Trucked (Ferrand 24 Tares
				Abatement - Tall Grass	Owner: In Alia January Profest 24 Trust - Tall Grass and weeds on the property
924 Forest St	8/8/2008	08 129292	Closed	PA - Parks Summary	Owner: R And J Enterprises Trustee/Forest 24 Trust -
924 Forest St	8/4/2008	08 125660	Resolved	CS - CSO Complaint - Tall	TGW 331
924 Forest St	6/16/2008	08 094207	Pesol	PA Parks Summan	
				Abatement - Garbage	Ownier: K And J Enterprises Trustee/Forest 24 Trust - Remove all discarded furniture, scrap wood, metal etc.
924 Forest St	6/16/2008	08 094208	Closed	Rubbish PA - Parks Summary	Owner: R And J Enterprises Trustee/Forest 24 Trust -
				Abatement - Tall Grass	Tall Grass and weeds on the property

$\geq$	ı
~	Ì
೭	ı
Š	ł
-	ļ
-	ı
~	ŀ
Ξ	I
ج.	į
+	ı
×	ł
	Į
3	ı
L	۱
ø	ı
õ	ı
0	ì
~	ı
_	ł
ο,	l
2	۱
-	١
~	١

Address         In Date           924 Forest St         6/9/2008           924 Forest St         6/9/2008           924 Forest St         6/9/2008           924 Forest St         6/2/2008           924 Forest St         6/2/2008		# 4			
	800		Status	Type	Description
	. '	08 089958	Inspected	VB - Vacant Building - Category 2 - Duplex	Stated Owner: MN Reo Property Maintenance - VB Monitoring Owner to convert to SFD, present use is Duplex. KE 2-18-
	800	08 089959	Open	Fee -	Owner: Yee Fang - VB Fee
	800	888888	Under Review	CS - CSO Complaint - Vacant Vaulding Monitoring - Complaint	VB Monitoring 09/16/2008 Dumping at rear. 9/22/08 the dump is on Duchess side - There is a large and growing mound of trash, old furniture and debris 11-18-08 SPRW Shut Off List 11-06-08 thru 11-12-08
	800	08 085520	Closed	RF - Referral - Citizen Complaint	Owner: R And J Enterprises Trustee/Forest 24 Trust - 06-02-08 Xcel Shut off list for Gas and/or Electric for unit 1
	800	08 085519	Transferred - Closed	CS - CSO Complaint - Shut Off - Complaint	Transferred - CS - CSO Complaint - Shut Off 06-02-08 Xcel Shut off list for Gas and/or Electric for unit Closed - Complaint 1
924 Forest St 7/24/2007	2007	07 120708	Resolved	CS - CSO Complaint - Exterior - Complaint	CS - CSO Complaint - Exterior trash in driveway (face on Duchess St.), doesn't know if - Complaint they have a hauler, on going problem.
924 Forest St 6/21/2007	2007	07 100029	Closed	CS - CSO Complaint - Exterior - Complaint	CS - CSO Complaint - Exterior Overflowing garbage in the rear Complaint 7/9/07: Per Excel Energy: Gas and/or Electric service shut off.
924 Forest St 5/15/2007	2007	07.078398	Closed	PA - Parks Summary Abatement - Garbage Rubbish	Owner: Melvin Robinson/Trenece Jones - Remove, tire, wood, branches shopping cart, loose scattered debris, bag of garbage, anything outside containers-
924 Forest St 5/15/2007	2007	07 078399	Closed	PA - Parks Summary	Owner: Melvin Robinson/Trenece Jones - Cut Tall Grass
924 Forest St 5/1/2007	2003	07 070565	Revoked/Va cant		CO - Certificate of Occupancy Responsible Party: Melvin Robinson Trenece Jones - Residential 1 Unit
925 Forest St Fl 1 5/1/2007	2003	07 070565	Revoked/Va cant	CO - Certificate of Occupancy - Residential 1 Unit	Revoked/Va CO - Certificate of Occupancy Responsible Party: Melvin Robinson Trenece Jones cant - Residential 1 Unit
925 Forest St Fl 2 5/1/2007	1007	07 070565	Revoked/Va cant	CO - Certificate of Occupancy - Residential 1 Unit	CO - Certificate of Occupancy Responsible Party: Melvin Robinson Trenece Jones - Residential 1 Unit

istory	
tivity H	
erty Ac	
P Prope	
AM	

	tioners transfer in the second				
Address	<u>In Date</u>	# QI	Status	Type	Description
924 Forest St	4/20/2007	07 065298	Closed	CS - CSO Complaint - Exterior (	Garbage/Rubbish.
924 Forest St	3/3/2007	07 037825	History	CO - Certificate of Occupancy F	CO - Certificate of Occupancy Responsible Party: Melvin Robinson Trenece Jones - Residential
926 Forest St Fl 1	3/3/2007	07 037825	History	CO - Certificate of Occupancy I	- Certificate of Occupancy Responsible Party: Melvin Robinson Trenece Jones ssidential
926 Forest St Fl 2	3/3/2007	07 037825	History	CO - Certificate of Occupancy	CO - Certificate of Occupancy Responsible Party: Melvin Robinson Trenece Jones - Residential
924 Forest St	12/15/2006	06 287241	History	TH - Truth In Sale of Housing Inspection - Duplex	Evaluator: Scott Scheunemann Scheunemann Home Services, Inc
924 Forest St	12/4/2006	06 280491	Closed	CS - CSO Complaint - Exterior I	CS - CSO Complaint - Exterior Pile of trash in rear of property.
924 Forest St	10/12/2006	06 243456	Closed	CS - CSO Complaint - Interior - Complaint	CS - CSO Complaint - Interior - 10-12-06 Gas and/or Electric shut off 09-22-06 as Complaint
924 Forest St	5/2/2005	05 096068	Finaled	E - Electrical Permit - Service (& Circuits - Residential Repair/Alter	Contractor: Bunton Electric
924 Forest St	11/4/2004	04 187501	Closed	CS - CSO Complaint - Exterior GARBAGE/RUBBISH - Complaint	GARBAGE/RUBBISH
924 Forest St	4/8/2004	04 068727	History	TH - Truth In Sale of Housing Inspection - Duplex	Evaluator: Richard Olson DANRICH Inspection Services
924 Forest St	1/29/2004	04 036529	Closed	CF - CSO Information Request - Information -	Vehicles in driveway w/ expired tabs; one of them is an RV type vehicle
924 Forest St	1/28/2004	04 035970	Closed	CS - CSO Complaint - Parking - No Response Required	CS - CSO Complaint - Parking - Vehicles in drive w/expired tabs; neighbors want FYI - No Response Required removed. One maybe RV vehicle.
924 Forest St	1/15/2004	04 023935	History	RR - Rental Registration - Duplex	RR Stated Owner: Ann Marie Reed - 03/03/2007: RR-CO Conversion: Folder status changed to History.
924 Forest St	10/24/2003	03 381686	Closed	CS - CSO Complaint - Exterior I - Complaint	CS - CSO Complaint - Exterior Discarded items, garbage/trash - Complaint

٠.	
STAMP Property Activity History	

Address	In Date	# QI	Status	Type	Description
924 Forest St	10/24/2003	03 381679	Closed	CS - CSO Complaint - Zoning -	CS - CSO Complaint - Zoning - Trailer on property used for living quarters
924 Forest St	1/3/2002	CN0730 CD	2000	Collipianii P. P. Ildian P. T. T.	
	7007/6/4	02 007 042	closed		Contractor: Giertsen Company Of Minnesota Inc - The
		-	without	Family/Duplex - Repair	following "Trade" Permits are required for this project:
		,	Approval		Electrical, . Closed without final approval
924 Forest St	11/26/2001	01 237104	Finaled	VB - Vacant Building -	Stated Owner: Danald W. Edicka
				Category 1 - Dinlex	Carea Correct Correct W 1 Olske
924 Forest St	11/21/2001	01 236794	Finaled	E - Electrical Permit - Service	E - Electrical Permit - Service   Contractor: Brite Lite Electric CO
			,	& Circuits - Residential	
				Repair/Alter	
924 Forest St	11/15/2001	01 235689	Closed	CS - CSO Complaint - Vacant	Vacant Building Monitoring
				Complaint	
924 Forest St	9/8/2001	02 212820	History	TH - Truth In Sale of Housing	Evaluator: Vicki Scheimemann Scheimemann Home
					Inspections
		•		Dwelling	
924 Forest St	8/28/1998	98 147301	Closed	E - Electrical Permit -	Contractor: Thomas Shock Shock Electric Inc - Closed
			without	Electrical - Residential	without final approval
			Approval	Repair/Alter	
924 Forest St	1/29/1998	98 103132	Closed	PL - Plumbing & Gas Fitting	Contractor: David Smith St Paul Plbg & Htg CO - Closed
			without		without final approval
			Approval	Residential Repair/Alter	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street,, Suite 220 St Paul, Minnesota 55101-1806 Telephone: 651-266-9090 Facsimile: 651-266-9099 Web: www.stpaul.gov/dsi

# **Code Compliance Report**

March 19, 2009

MN REO PROPERTY MAINTENANCE 8937 AZTEC DRIVE EDEN PRAIRIE MN 55347

Re:

924 Forest St

File#: 08 089958 VB2

Dear Property Owner:

The following is the Code Compliance report you requested on February 26, 2009.

Please be advised that this report is accurate and correct as of the date March 03, 2009. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from March 03, 2009. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected:

#### **BUILDING**

- 1. Remove ceiling in first floor kitchen and install one hour fire rated assembly between units.
- 2. No access to basement install code approved stairs in new location.
- 3. The second floor northwest corner bedroom install window that meets egress requirements.
- 4. Insure basement cellar floor is even, is cleanable, and all holes are filled.
- 5. Install handrails and guardrails at all stairways, including basement stairways, per attachment.
- 6. Strap or support top of stair stringers.
- 7. Install plinth blocks under posts in basement as needed.
- 8. Tuck Point interior/exterior of foundation.
- 9. Maintain one-hour fire-separation between dwelling units and between units and common areas.
- 10. Install 20-minute fire-rated doors, with self-closing device, between common areas and individual units.
- 11. Install tempered or safety glass in window over stair landing to Code.
- 12. Install tempered or safety glass in window over bathtub to Code.
- 13. Provide thumb type dead bolts for all entry doors. Remove any surface bolts.

Page 2

#### **BUILDING**

- 14. Repair or replace any deteriorated window sash, broken glass, sash holders, re-putty etc. as necessary.
- 15. Provide complete storms and screens, in good repair, for all door and window openings.
- 16. Repair walls, ceilings and floors throughout, as necessary.
- 17. Provide fire block construction as necessary.
- 18. Prepare and paint interior and exterior as necessary. Observe necessary abatement procedure if lead base paint is present (See St. Paul Legislative Code, Chap. 34 for additional information).
- 19. Any framing members that do not meet code (where wall and ceiling covering is removed, members that are over-spanned, over-spaced, not being carried properly, door and window openings that are not headered, etc.) are to be reconstructed as per code.
- 20. Provide general clean-up of premise.
- 21. Provide smoke detectors per the Minnesota Building Code and carbon monoxide detectors per State law.
- 22. Repair siding, soffit, fascia, trim, etc. as necessary.
- 23. Provide weather-sealed, air-sealed, and vermin-sealed exterior.
- 24. Provide proper drainage around house to direct water away from foundation.
- 25. Maintain 6 inches minimum clearance between wood and soil, sloped to drain away from foundation.
- 26. Install downspouts and a complete gutter system on north side of house.
- 27. Install rain leaders to direct drainage away from the foundation.
- 28. Weather-seal exterior doors.
- 29. Dry out basement and eliminate source of moisture.
- 30. Provide durable, dustless parking surface as specified in the zoning code.

#### **ELECTRICAL**

- 1. **Note:** Inspector did not have proper access to the basement.
- 2. Bond around water meter with a copper wire sized for the electrical service per Article 250 of the NEC
- 3. Provide a complete circuit directory at service panel indicating location and use of all circuits
- 4. Verify/install a separate 20 ampere laundry circuit & a separate 20 ampere kitchen appliance circuit
- 5. Verify that fuse/circuit breaker amperage matches wire size
- 6. Properly strap cables and conduits in basement/ service conduit on the exterior of the house
- 7. Provide one (1) light for each 200 square feet in unfinished basement. One light must be switched from the top of the stairs
- 8. Remove all cord wiring
- 9. Repair or replace all broken, missing or loose light fixtures, switches & outlets, covers and plates
- 10. Check <u>all</u> outlets for proper polarity and verify ground on 3-prong outlets.
- 11. Remove any 3-wire ungrounded outlets and replace with 2-wire or ground 3-wire to code

Page 3

#### **ELECTRICAL**

12. Throughout building, install outlets and light fixtures as specified in Bulletin 80-1

- 13. Install hard-wired, battery backup smoke detector as specified in Bulletin 80-1 and other smoke detectors as required by the IRC. Also, Install carbon monoxide detector(s) within 10 feet of all bedrooms.
- 14. Remove and/or rewire all illegal, improper or hazardous wiring in basement
- 15. Duplex: Check Building write-up for fire resistance requirements if both panels are in the common area in a basement or move 2<sup>nd</sup> unit electrical panelboard to the second unit.
- 16. All added receptacles must be grounded, tamper-resistant and be on an Arc-Fault Circuit Interrupter-protected circuit.
- 17. All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.
- 18. Any open walls or walls that are opened as part of this project must be wired to the standards of the 2008 NEC.
- 19. All buildings on the property must meet the St. Paul Property Maintenance Code (Bulletin 80-1).
- 20. Properly mount baseboard heater.
- 21. Properly run/remove illegal romex in kitchen.

#### **PLUMBING**

All plumbing work requires permit(s) and must be done by a plumbing contractor licensed in Saint Paul.

#### **Basement**

#### Water Heaters on First and Second Floor:

Temperature and pressure relief discharge piping is incorrect

No gas shutoff or gas piping is incorrect

Gas venting is incorrect

Vent must be in chimney liner

Water piping is incorrect.

Not fired or in service.

#### Water Meter:

Meter is removed and not in service.

#### Water Piping:

Repair or replace all corroded, broken or leaking water piping.

Water pipe sizing is incorrect.

#### Soil and Waste piping:

No front sewer cleanout and no soil stack base cleanout.

Improper pipe supports, connections, transitions, fittings or pipe usage.

Replace corroded cast iron or steel waste piping.

The second floor bathroom fixtures tie into first floor plumbing vent, must correct to code.

#### First Floor

The lavatory waste is incorrect and un-vented.

The bathtub waste and water piping is incorrect and incorrectly vented.

Page 4

#### **PLUMBING**

#### Second Floor

The kitchen sink waste is incorrect and un-vented.

The lavatory waste is incorrect and incorrectly vented.

The bathtub waste is incorrect and incorrectly vented.

The range gas shutoff, connector or gas piping is incorrect.

#### Exterior

The lawn hydrant(s) requires backflow assembly or device.

#### **HEATING**

- 1. Install approved lever handle manual gas shutoff valve on first floor wall furnace.
- 2. Install approved lever handle manual building shutoff gas valve in an accessible location ahead of the first branch tee in each dwelling unit.
- 3. Clean and Orsat test second floor furnace and first floor wall furnace burners. Check all controls for proper operation. Check furnace heat exchangers for leaks; provide documentation from a licensed contractor that the heating units are safe.
- 4. Provide thirty (30) inches of clearance in front of second floor furnace for service.
- 5. Replace second floor furnace venting to manufacturer's installation instructions.
- 6. Provide adequate clearance from flue vent pipe on first floor furnace to combustible materials or provide approved shielding according to code.
- 7. Vent clothes dryer to code.
- 8. Provide adequate combustion air and support duct to code.
- 9. Provide support for gas lines to code.
- 10. Plug, cap and/or remove all disconnected gas lines.
- 11. Install furnace air filter access cover.
- 12. Clean all supply and return ducts for warm air heating system.
- 13. Repair and/or replace heating registers as necessary.
- 14. Re-pipe condensate drain on second floor furnace according to manufacturer's instructions.
- 15. Verify gas piping to second floor furnace is adequately sized.
- 16. Provide heat in every habitable room and bathrooms.
- 17. There was no access to basement and attic at time of inspection. If there is mechanical equipment, duct work, etc. in these areas they must be brought up to code.
- 18. A gas mechanical permit is required and possibly a warm air permit for the above work.

#### **ZONING**

1. This house was inspected as a duplex.

Page 5

#### **NOTES**

See attachment for permit requirements and appeals procedure.

Roof, sidewalks, etc. snow covered and could not be inspected. All must meet appropriate codes when completed.

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.)

If you have any questions regarding this inspection report, please contact Jim Seeger between 7:30 – 9:00 AM at 651-266-8989 or leave a voice mail message.

Sincerely,

James L. Seeger Code Compliance Officer JLS:ml Attachments

# Department of Safety and Inspections VACANT BUILDING REGISTRATION FORM

Date: Address of Property: 924 Forest	St. St. Paul, MN
Planned disposition of this building (please check one plan to rehabilitate this structure commencing (date	e):
I plan to demolish (wreck and remove) this building	
I am willing to authorize the City of Saint Paul to de	
This building is vacant as a result of fire damage. The property owner, want to claim registration and for date of the fire. I intend to repair and reoccupy the Other:	The fire occurred on (date) . I, as fee exemption status for ninety (90) days from the building.
Persons who will be responsible for compliance with the	requirements of ordinance:
NAME ADDRESS HOM	IE NO. WORK NO.
Yee Fang 651	•
1 0 31	373
NAME ADDRESS HOM	AE NO. WORK NO.
Print Your Name (legibly)  Print Your Name (legibly)  Signature  Print Your Name (legibly)  Date of Birth  Date of Birth  Print Your Name (legibly)  Signature  Date of Birth  Signature  State  State  Zip  State  L51-335-8664  main contact telephone  alternate phone	INSTRUCTIONS:  Complete and return this form with your VB registration fee payment of \$1,100.00.  Make checks payable to: City of Saint Paul Credit cards are accepted  Make Payment at, or mail payment to:  City of Saint Paul  Department of Safety and Inspections  Code Enforcement — Vacant Buildings  375 Jackson Street, Suite 220  St. Paul, MN 55101-1806
mail address	Thank you for your cooperation



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street , Suite 220 St Paul, Minnesota 55101-1024 Telephone: 651-266-9090 Facsimile: 651-266-9099 Web: <u>www.stpaul.gâv/dsi</u>

## Residential Use Affidavit

I, (Printed Name) / own the residence at (ad-	ee Fang dress) 929	Forest St.	, the unders	igned, certify that I in St. Paul, MN.
I purchased this property with two kitchens)	y in (year) 2010 Single Famili	as a (Single Fa	mily with one k	itchen or Duplex
This property has been c kitchens) 5,25	K tamil	/		
This property has been u	ised since purchase	as a (Single famil	y or Duplex)	inste Family
7.	Can.		2-10-	-/0
Signature (Homeown	ier)	· I	Date	
Property zoning R	2	in by zoning staff		agen de la minera asseption de montre es mandre condition secundo especie de filològica de la condition de la
Truth in Housing Info_		± 1	***************************************	
Certificate of Occupancy	y		t .	
History Check				
Address Folder	· · · · · · · · · · · · · · · · · · ·			
Ramsey County				*
Action taken Property	1 is curre	utly adup	ley, per ?	Tou Seign- tield inspection.
Zoning Staff	Karen Zacha	)	Date	2,17.10

An Affirmative Auction Equal Opportunity Employer

From:

Tom Ferrara

To: CC: y2k2000family@yahoo.com Hawkins, Jeff; Soley, Reid

Date:

3/31/2010 4:43 PM

Subject:

924 Forest Ave - EFV Extension 10598020006.DOC

Attachments:

10598020006.DOC

YEE FANG 957 REANEY AVE ST PAULMN 55106

y2k2000family@yahoo.com ( mailto:y2k2000family@yahoo.com )

RE: 924 Forest Ave / March 29, 2010 Summary Abatement Order

Your extension request has been granted and the compliance deadline for the above referenced order has been extended to 4/16/10. Therefore, a complete application to reestablish a legal-nonconforming duplex use there must be submitted to the Planning Commission and/or the property brought into compliance as originally ordered (requirement pasted below) prior to 4/16/10. If this property is not brought into compliance, a work order for the City and/or its representatives to install an EFV will be placed without further notice given to you. However, please note that you may be bound to renovating the property as a single family dwelling, per the Zoning-Residential Use affidavit you signed 2/10/10 stating the property was to be converted to single family use and the 2/17/10 sale approval granted partly upon the receipt/requirement of that affidavit.

3/29/10 Order Text

Shut off the gas and water services at the above referenced property or install an excess gas flow valve (EFV) after each gas meter serving the building(s) in order to decrease the risk of fire, explosion or related dangerous conditions.

If you do not correct the nuisance or file an appeal before April 9, 2010, the City will correct the nuisance and charge all costs, including boarding costs, against the property as a special assessment to be collected in the same way as property taxes.

If the City corrects the nuisance, the charges will include the cost of correction, inspection, travel time, equipment, etc. The rate will be approximately \$260.00 per hour, plus expenses for abatement and a minimum of \$375.00 per excess flow valve installed.

**Thank You** 

Thomas Ferrara
City of Saint Paul,
Department of Safety & Inspections
(651) 266-9087
Fax (651) 266-1919
tom.ferrara@ci.stpaul.mn.us



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-1919 Web: www.stpaul.gov/dsi

February 17, 2010

Yee Fang 957 Reaney Ave St Paul MN 55106

Re: 924 FOREST ST

Chapter 33 of the Saint Paul Legislative Code restricts the sale of Category II Registered Vacant Buildings. Sale of the above referenced address to <u>Yee Fang</u> is approved based on the City's review of the following requirements:

- 1. Application Fee Paid.
- 2. Zoning Status Approved.
- 3. Registration of Ownership Updated.
- 4. Vacant Building Fees Current.
- 5. Code Compliance Inspection Report Issued.
- 6. Cost Estimates from Licensed Contractors for Code Compliance Work Submitted.
- 7. Schedule for Completion of Code Compliance Work Submitted.
- 8. Proof of Financial Capability Verified.

If you have any questions regarding this matter, you may contact me at 651-266-9120.

Sincerely,

Reid Soley CSO CE Staff

vb33sale60201 12/09

#### Luis Pereira - ZF #10-314-094: 924 Forest

From:

Luis Pereira

To:

seatanf@yahoo.com

Subject:

ZF #10-314-094: 924 Forest

Hi Chao,

Here are the required findings that I need to make in my staff report. The one that I was having the most trouble with is the following requirement:

(1) The structure, or structure and land in combination, cannot reasonably or economically be used for a conforming purpose (Single Family Use).

This is where some additional information would be helpful about the cost difference between fixing the property up as a duplex versus converting it to a single family use and fixing it up.

Here are all the findings, for your reference At this point, these findings can be made, from my perspective:

- 2. Section 62.109(e) states: When a nonconforming use of a structure, or structure and land in combination, is discontinued or ceases to exist for a continuous period of three hundred sixty-five (365) days, the planning commission may permit the reestablishment of a nonconforming use if the commission makes the following findings:
  - (1) The structure, or structure and land in combination, cannot reasonably or economically be used for a conforming purpose.
  - (2) The proposed use is equally appropriate or more appropriate to the district than the previous nonconforming use.
  - (3) The proposed use will not be detrimental to the existing character of development in the immediate neighborhood or endanger the public health, safety, or general welfare.
  - (4) The proposed use is consistent with the comprehensive plan.
  - (5) A notarized petition of two-thirds of the property owners within one hundred (100) feet of the property has been submitted stating their support for the use.
- 3. The Planning Commission has established guidelines for applications to establish legal nonconforming use status for duplexes. While not themselves requirements, these guidelines lay out additional more objective factors the Planning Commission wishes to consider in determining if the required findings for granting nonconforming use permits listed in §62.109 of the Zoning Code can be made. The Planning Commission's Duplex Conversion Guidelines state that for applications for nonconforming use permits for duplexes in residential districts, staff will recommend denial unless the following guidelines are met:
  - A. Lot size of at least 5,000 square feet with a lot width or front footage of 40 feet.
  - B. Gross living area, after completion of duplex conversion, of at least 1,500 square feet.
  - C. Three off-street parking spaces (non-stacked) are preferred; two spaces are the required minimum.
  - D. All remodeling work for the duplex is on the inside of the structure unless the plans for exterior changes are approved by the Board of Zoning Appeals as part of the variance. (The Planning Commission will approve these changes for the cases they handle.)
- E. For the purpose of protecting the welfare and safety of the occupants of any structure that has been converted into a duplex without the necessary permits, a code compliance inspection shall be conducted and the necessary permits obtained to bring the entire structure into conformance with building and fire code standards; or the property owner must, as a condition of the approval, make the necessary improvements to obtain the necessary permits and bring

the entire structure into building and fire code compliance within the time specified in the resolution.

Fax 651-770-1680

Thanks,

Luis

Chao - see Next page. Can a cost for "rehab projects" and
"Annual rehab debt prynent" be estimated for both star


Single Family use versus Duplex use?

Thanks,

Luis

266-6591 (phone)

Luis, pereira @ci.st paul.mn.us



**Fig. 1.** Eastern view of 924 Forest St




Fig. 2. Southeast view of properties to the south of 924 Forest St.



Fig. 3. Western view of the rear of 924 Forest St; existing two-car parking area



Fig. 4. Northwestern view of the rear of 924 Forest St; area adjacent to two-car parking area

